

TECH TIPS

PRODUCT: Refrigerator TIP VERSION: REF02-003

MODEL: RS2533SW, RS2555SW, RS2555SL, RS2577SW & RS2577SL

SUBJECT: Water leaking at the filter.

SYMPTOM: Water leaking at the filter.

REMARKS: If the filter is installed incorrectly, it will leak water.

REPAIR: Please make sure you line up the filter correctly to avoid water leak.

INTSRUCTIONS: 1. Turn the water filter 1/2 turn counterclockwise and pull it down.

2. To install the filter, align the indication mark (unlock position)

and push it up while turning ½ turn clockwise until the lock position is aligned. Do not over tighten.



Note: If the filter is removed, you will still get water to the icemaker and water dispenser.