

CABIN AIR FILTER REPLACEMENT

Recommended Replacement Interval: 15,000 miles under normal operating conditions.

2017 Chrysler Pacifica

Installation Time: 5-10 min

Tools needed: None

Location: Behind Glove Box

1. Open glove box.
2. Lower the glove box further by squeezing the retainers near the top.
3. Remove the retaining cable to allow removal of glove box.
4. The HVAC door is located behind a decorative shield. Three retaining clips can be removed by pressing in on each.
5. Open HVAC door and replace filter taking note of flow direction arrow (marked on filter).
6. Reassemble.