

CABIN AIR FILTER REPLACEMENT

Recommended Replacement Interval: 15,000 miles under normal operating conditions.

'05-'05 Hyundai Tucson (w/ Auto AC)

'06-'07 Kia Rio (Sedan/Hatchback)

'05-'06 Kia Sportage

Installation Time: 5 min

Tools needed: No

Location: Behind the glove compartment

1. Open glove compartment and push inwards on retaining latches to remove.
2. Remove black retainer string which is attached to the glove box.
3. Glove box can now swing down and stay open.
4. Once the glove box is down, the filter access door will be visible.
5. Push on 2 retaining tabs on each side to release the filter access door.
6. Slide filter frame out of compartment.
7. Replace filter with the flow arrows pointing down and slide back into compartment.
8. Reassemble in reverse order.

Note: For those models that do not have a factory equipped cabin air filter, remove the empty frame and replace with new filter